

PWS

Haskel Booster Repair

Work Required

Haskel Air-Driven Booster Model 26968 S/N: 5352011-1 and S/N: 5352011-2 requires shipment to a manufacturer for rebuild and inspection of O2 Booster Pump. The rebuild should consist of the below requirements at a minimum.

- Replacement of normal wear items like seals
- Cleaning refurbishment or replacement on gauges (if applicable)
- General cleaning and inspection of all components to Haskel spec
- Functional checks according to the Haskel manual requirements.

Inspection of work required.

Once the flight receives the repaired Haskel Booster they will due a visual inspection making sure all components are cleaned followed by performing an operational test consisting of pumping their oxygen bottle from 2500 PSI to 2100 PSI.